# Lecture 2 Something you need to remember about Statistics - II.

Useful book: J.C.Miller and J.N.Miller, *Statistics for Analytical Chemistry*, 3rd edition, 1993.

#### Gaussian distribution



Confidence interval. The sampling distribution of the mean William Sealy Gosset (1876 – 1937)



## SIGNIFICANCE TESTS.

Null hypothesis: our method is not a subject to systematic error.

### COMPARISON OF MEANS WITH STUDENT'S t

1. Comparison of an experimental mean with a known value.

2. Comparison of the means of two samples (comparing two sets of replicate measurements).

3. Paired t-test: comparison of two analytical methods.

COMPARISON OF STANDARD DEVIATIONS WITH THE F TEST.

# BAD DATA TESTING WITH THE Q TEST.

Use Q test to reject "bad" data points.

#### Appendix B

	Confidence level (%)						
Degrees of freedom	50	90	95	98	99	99.5	99.9
1	1.000	6.314	12.706	31.821	63.656	127.321	636.578
2	0.816	2.920	4.303	6.965	9.925	14.089	31.598
3	0.765	2.353	3.182	4.541	5.841	7.453	12.924
4	0.741	2.132	2.776	3.747	4.604	5.598	8.610
5	0.727	2.015	2.571	3.365	4.032	4.773	6.869
6	0.718	1.943	2.447	3.143	3.707	4.317	5.959
7	0.711	1.895	2.365	2.998	3.500	4.029	5.408
8	0.706	1.860	2.306	2.896	3.355	3.832	5.041
9	0.703	1.833	2.262	2.821	3.250	3.690	4.781
10	0.700	1.812	2.228	2.764	3.169	3.581	4.587
15	0.691	1.753	2.131	2.602	2.947	3.252	4.073
20	0.687	1.725	2.086	2.528	2.845	3.153	3.850
25	0.684	1.708	2.060	2.485	2.787	3.078	3.725
30	0.683	1.697	2.042	2.457	2.750	3.030	3.646
40	0.681	1.684	2.021	2.423	2.704	2.971	3.551
60	0.679	1.671	2.000	2.390	2.660	2.915	3.460
120	0.677	1.658	1.980	2.358	2.617	2.860	3.373
œ	0.674	1.645	1.960	2.326	2.576	2.807	3.291

#### Table 4-2 Values of Student's t

NOTE: In calculating confidence intervals,  $\sigma$  may be substituted for s in Equation 4-6 if you have a great deal of experience with a particular method and have therefore determined its "true" population standard deviation. If  $\sigma$  is used instead of s, the value of t to use in Equation 4-6 comes from the bottom row of Table 4-2.

Table 4-2

Quantitative Chemical Analysis, Seventh Edition

© 2007 W. H. Freeman and Company

Degrees of	f Degrees of freedom for s <sub>1</sub>													
freedom for s <sub>2</sub>	2	3	4	5	6	7	8	9	10	12	15	20	30	8
2	19.0	19.2	19.2	19.3	19.3	19.4	19.4	19.4	19.4	19.4	19.4	19.4	19.5	19.5
3	9.55	9.28	9.12	9.01	8.94	8.89	8.84	8.81	8.79	8.74	8.70	8.66	8.62	8.53
4	6.94	6.59	6.39	6.26	6.16	6.09	6.04	6.00	5.96	5.91	5.86	5.80	5.75	5.63
5	5.79	5.41	5.19	5.05	4.95	4.88	4.82	4.77	4.74	4.68	4.62	4.56	4.50	4.36
6	5.14	4.76	4.53	4.39	4.28	4.21	4.15	4.10	4.06	4.00	3.94	3.87	3.81	3.67
7	4.74	4.35	4.12	3.97	3.87	3.79	3.73	3.68	3.64	3.58	3.51	3.44	3.38	3.23
8	4.46	4.07	3.84	3.69	3.58	3.50	3.44	3.39	3.35	3.28	3.22	3.15	3.08	2.93
9	4.26	3.86	3.63	3.48	3.37	3.29	3.23	3.18	3.14	3.07	3.01	2.94	2.86	2.71
10	4.10	3.71	3.48	3.33	3.22	3.14	3.07	3.02	2.98	2.91	2.84	2.77	2.70	2.54
11	3.98	3.59	3.36	3.20	3.10	3.01	2.95	2.90	2.85	2.79	2.72	2.65	2.57	2.40
12	3.88	3.49	3.26	3.11	3.00	2.91	2.85	2.80	2.75	2.69	2.62	2.54	2.47	2.30
13	3.81	3.41	3.18	3.02	2.92	2.83	2.77	2.71	2.67	2.60	2.53	2.46	2.38	2.21
14	3.74	3.34	3.11	2.96	2.85	2.76	2.70	2.65	2.60	2.53	2.46	2.39	2.31	2.13
15	3.68	3.29	3.06	2.90	2.79	2.71	2.64	2.59	2.54	2.48	2.40	2.33	2.25	2.07
16	3.63	3.24	3.01	2.85	2.74	2.66	2.59	2.54	2.49	2.42	2.35	2.28	2.19	2.01
17	3.59	3.20	2.96	2.81	2.70	2.61	2.55	2.49	2.45	2.38	2.31	2.23	2.15	1.96
18	3.56	3.16	2.93	2.77	2.66	2.58	2.51	2.46	2.41	2.34	2.27	2.19	2.11	1.92
19	3.52	3.13	2.90	2.74	2.63	2.54	2.48	2.42	2.38	2.31	2.23	2.16	2.07	1.88
20	3.49	3.10	2.87	2.71	2.60	2.51	2.45	2.39	2.35	2.28	2.20	2.12	2.04	1.84
30	3.32	2.92	2.69	2.53	2.42	2.33	2.27	2.21	2.16	2.09	2.01	1.93	1.84	1.62
œ	3.00	2.60	2.37	2.21	2.10	2.01	1.94	1.88	1.83	1.75	1.67	1.57	1.46	1.00

Appendix C Table 4-4 Critical values of  $F = s^2/s^2$  at 95% confidence level

Table 4-4Quantitative Chemical Analysis, Seventh Edition© 2007 W. H. Freeman and Company

# Appendix D

Q (90% confidence) <sup>a</sup>	Number of observations	
0.76	4	
0.64	5	
0.56	6	
0.51	7	
0.47	8	
0.44	9	
0.41	10	

#### Table 4-5 Values of Q for rejection of data

a. Q = gap/range. If  $Q_{calculated} > Q_{table'}$  the value in question can be rejected with 90% confidence.

SOURCE: R. B. Dean and W. J. Dixon, Anal. Chem. **1951**, 23, 636; see also D. R. Rorabacher, Anal. Chem. **1991**, 63, 139.

Table 4-5 Quantitative Chemical Analysis, Seventh Edition © 2007 W.H.Freeman and Company

Q	Number of
(95%	observations
confidence)	
0.831	4
0.717	5
0.621	6
0.570	7
0.524	8
0.492	9
0.464	10