

A (growing) summary of problems and solutions encountered in the past.

Problem: Hall Measurement Software (HMS) won't communicate with Magnet Power Supply (MPS)

Solution: Check the VI "mode" switches on the back of the power supply. Make sure they are switched to "EXT" mode (see page 2-5 of MPS Manual).